


MISSING PARTS OR IN NEED
OF
ASSEMBLY ASSISTANCE?

Contact us direct for fast friendly service (800) 433-8488


Int'l calls (630) 892-8941 | WEB: WWW.LYONWORKSPACE.COM | Fax (800) 367-6681


ASSEMBLY INSTRUCTIONS
FOR LYON TWO LEVEL
8000 SERIES SHELVING

LYON LYON WORKSPACE PRODUCTS
P.O. BOX 671
ISO 9001 AURORA, IL 60507

9260 36"
PASS THROUGH GATE

BILL OF MATERIALS		
QTY	DESCRIPTION	XX9260
1	GALVARAIL PIPE 22 5/8"	NF9P12091
2	GALVARAIL PIPE 31 1/2"	NF9P12093
1	GALVARAIL PIPE 43 15/32"	NF9P12098
1	BOLT PLATE ASSEMBLY	DD4718A11
4	GATE MTG BRACKET	DD4720P12
1	GATE MTG BRACKET (SPEC)	DD4720SP12
16	NUT 5/16-18 WAFFLE HEX	NFOP10285
8	5/16-18 X 3/4" HHCS	NFOP10287
4	1 1/4" PIPE TEE	NFOP10349
2	1 1/4" PIPE COLLAR	NFOP10352
2	5/16-18 X 2 3/8 "U" BOLT	NFOP10353
2	5/16-18 X 2 3/4 "U" BOLT	NFOP10354
2	PIPE CAP	NFOP10431
8	SPACER PLATE-ZINC PLATED	NF4720P11
1	CHANNEL BRACKET	DD4809P11





GENERAL INSTRUCTIONS

1. ASSEMBLE GATE AND BOLT PLATE ASSY AS SHOWN ABOVE
2. PLACE GATE ASSEMBLY ONTO 43 15/32" GALVARAIL PIPE
3. ADJUST PIPE COLLAR FOR FREE MOVEMENT OF GATE
4. ATTACH 31 1/2" PIPE TO TEE POST WITH GATE BRACKETS, SPACER PLATES, AND 5/16-18 X 2 3/4" U-BOLTS

MISSING PARTS OR IN NEED
OF
ASSEMBLY ASSISTANCE?

Contact us direct for fast friendly service (800) 433-8488

Int'l calls (630) 892-8941 | WEB: WWW.LYONWORKSPACE.COM | Fax (800) 367-6681

ASSEMBLY INSTRUCTIONS
FOR LYON TWO LEVEL
8000 SERIES SHELVING

LYON LYON WORKSPACE PRODUCTS
P.O. BOX 671
ISO 9001 AURORA, IL 60507

9260 36"
PASS THROUGH GATE