


MISSING PARTS OR IN NEED
OF
ASSEMBLY ASSISTANCE?

Contact us direct for fast friendly service (800) 433-8488


Int'l calls (630) 892-8941 | WEB: WWW.LYONWORKSPACE.COM | Fax (800) 367-6681


ASSEMBLY INSTRUCTIONS
FOR LYON TWO LEVEL
8000 SERIES SHELVING

LYON WORKSPACE PRODUCTS
P.O. BOX 671
AURORA, IL 60507

9261
PASS THROUGH GATE
48"

BILL OF MATERIALS		
QTY	DESCRIPTION	XX9261
1	GALVARAIL PIPE 22 5/8"	NF9P12091
3	GALVARAIL PIPE 43 15/32"	NF9P12098
1	BOLT PLATE ASSEMBLY	DD4718A11
4	GATE MTG BRACKET	DD4720P12
1	GATE MTG BRACKET (SPEC)	DD4720SP12
16	NUT 5/16-18 WAFFLE HEX	NFOP10285
8	5/16-18 X 3/4" HHCS	NFOP10287
4	1 1/4" PIPE TEE	NFOP10349
2	1 1/4" PIPE COLLAR	NFOP10352
2	5/16-18 X 2 3/8 "U" BOLT	NFOP10353
2	5/16-18 X 2 3/4 "U" BOLT	NFOP10354
2	PIPE CAP	NFOP10431
8	SPACER PLATE-ZINC PLATED	NF4720P11
1	CHANNEL BRACKET	DD4809P11





GENERAL INSTRUCTIONS

1. ASSEMBLE GATE AND BOLT PLATE ASSY AS SHOWN ABOVE
2. PLACE GATE ASSEMBLY ONTO 43 15/32" GALVARAIL PIPE
3. ADJUST PIPE COLLAR FOR FREE MOVEMENT OF GATE
4. ATTACH 43 15/32" PIPE TO TEE POST WITH GATE BRACKETS, SPACER PLATES, AND 5/16-18 X 2 3/4" U-BOLTS

MISSING PARTS OR IN NEED
OF
ASSEMBLY ASSISTANCE?

Contact us direct for fast friendly service (800) 433-8488

Int'l calls (630) 892-8941 | WEB: WWW.LYONWORKSPACE.COM | Fax (800) 367-6681

ASSEMBLY INSTRUCTIONS
FOR LYON TWO LEVEL
8000 SERIES SHELVING

LYON LYON WORKSPACE PRODUCTS
ISO 9001 AS9100
P.O. BOX 671
AURORA, IL 60507

9261
PASS THROUGH GATE
48"