


MISSING PARTS OR IN NEED
OF
ASSEMBLY ASSISTANCE?

Contact us direct for fast friendly service (800) 433-8488


Int'l calls (630) 892-8941 | WEB: WWW.LYONWORKSPACE.COM | Fax (800) 367-6681


ASSEMBLY INSTRUCTIONS
FOR LYON TWO LEVEL
8000 SERIES SHELVING


LYON WORKSPACE PRODUCTS
P.O. BOX 671
AURORA, IL 60507

9259
PERIMETER GATE 48"

BILL OF MATERIALS		
QTY	DESCRIPTION	XX9259
1	HANDRAIL COLUMN SUPPORT	XX4832P11
1	PREM GATE FIN TRIM 48	XX4840P12
1	GALVARAIL PIPE 22 5/8"	NF9P12091
2	GALVARAIL PIPE 46	NF9P120921
1	GALVARAIL PIPE 46 3/4"	NF9P12095
1	BOLT PLATE ASSEMBLY	DD4718A11
1	GATE LOCK BRACKET ASSY	DD4719A11
18	NUT 5/16-18 WAFFLE HEX	NFOP10285
6	5/16-18 X 3/4" HHCS	NFOP10287
6	1 1/4" PIPE TEE	NFOP10349
1	1 1/4" PIPE COLLAR	NFOP10352
6	5/16-18 X 2 3/8 "U" BOLT	NFOP10353
2	PIPE CAP	NFOP10431
12	SPACER PLATE-ZINC PLATED	NF4720P11







GENERAL INSTRUCTIONS

1. ASSEMBLE FINISH TRIM AND HANDRAIL COLUMN TO EXISTING KICKPLATE AND LALLY COLUMN
2. ATTACH GALVARAIL PIPE (46 3/4") TO HANDRAIL COLUMN SUPPORT USING "U" BOLTS AND SPACER PLATES
3. ASSEMBLE GATE AND BOLT PLATE ASSY AS SHOWN ABOVE
4. PLACE GATE ASSEMBLY ONTO HANDRAIL COLUMN AND INSTALL UPPER HANDRAIL
5. ADJUST PIPE COLLAR FOR FREE MOVEMENT OF GATE
6. INSTALL LATCH BRACKET AND CHECK FOR OPERABILITY

MISSING PARTS OR IN NEED
OF
ASSEMBLY ASSISTANCE?

Contact us direct for fast friendly service (800) 433-8488

Int'l calls (630) 892-8941 | WEB: WWW.LYONWORKSPACE.COM | Fax (800) 367-6681

ASSEMBLY INSTRUCTIONS
FOR LYON TWO LEVEL
8000 SERIES SHELVING

LYON LYON WORKSPACE PRODUCTS
ISO 9001 AS456
P.O. BOX 671
AURORA, IL 60507

9259
PERIMETER GATE 48"